APPENDIX E

Other Information

in accordance with the requirements of R645-301 and R645-302.

CONTENTS

Sediment Pond Certificate

SEDIMENT POND CERTIFICATE

GENWAL COAL COMPANY

1997 ANNUAL POND INSPECTION REPORT

POND: GENWAL SEDIMENT POND NO. 1 IMPOUNDMENTS	LOCATION: CRANDALL CANYON
(1) Stability	Slopes Stable. Pond Reconstructed.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	_12"
(5) Existing Storage Capacity	3.500 acre feet
(6) Monitoring Procedures	Quarterly Inspection /UPDES.
SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elev.	7891.00
(8) Sediment Cleanout Level (Ele	v.) <u>7894.00</u>
(9) Principle Spillway (Elev.)	7905.81
(10) Emergency Spillway (Elev.)	7906.81
(11) Existing Sediment Capacity	0.325 acre feet
(To Cleanout)	
<u>GENERAL</u>	
(12) Comments/Recommendations	Pond enlarged and reconstructed in 1997.
	Toomberdeed In 1797.
STATEMENT	

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

(Signature)

11/21/97 (Date)

<u>SEDIMENT POND CERTIFICATION</u> (Construction Certification)

Company Name and Address:	<u>Genwal Coal Company</u>
	P.O. Box 1420
	Huntington, Utah 84501
Permit Number:	ACT/015/032
Pond Location:	Crandall Canyon
Pond Identification:	Genwal Sediment Pond No.1

Certification Statement:

I hereby certify that I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the construction of the impoundments in accordance with the certified and approved design for this structure; the materials and conditions required for construction are in accordance with approved design and meet or exceed the minimum design requirements; and, that inspections of the impoundment were made during critical periods of the construction by or under my direction in accordance with the requirements of regulation R645-301-514-300.



Signature Signature

11/21/97 Date

GENWAL COAL COMPANY POND INSPECTION REPORT (Final Inspection)

POND: Genwal Sediment Pond No. 1	LOCATION: Crandall Canyon
ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(1) Totoncial balety hazalus	None Noted.
(2) Slope Stability	Slopes appear stable - Hydroseeded.
(3) Erosion	None Evident. Rip-rapped
	inlets and silt fence - O.K.
(4) Construction and Maintenance	Pond constructed according to
Performance Standards	plan. Inlets rip-rapped,
	Emergency Spillway -
	Concrete.
(5) Recommendations/Comments	Constructed pond has a capacity of 3.572 ac. ft. at the principle spillway, 2.488 ac. ft. required - O.K.

STATEMENT

I have performed the above inspection on this pond and do hereby certify it to be a true and accurate representation of the pond at this time.

